Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513
Inspection Date(s): 2/25/2014, 2/26/2014, 2/27/2014	Man Days: 3
Inspection Unit: Belleville/E. St. Louis	•
Location of Audit: Trenton, East St. Louis, O'Fallon	
Exit Meeting Contact: Dallas Jett	
Inspection Type: Design Testing and Construction	
Pipeline Safety Representative(s): Valerie Schwing	
Company Representative to Receive Report: Michael Fuller	
Company Representative's Email Address: mfuller2@ameren.com	

CONSTRUCTION INFORMATION				
Construction Performed By:				
Ameren				
Person(s) On Job Site				
Ricky Duncan	Shaun Hattan			
	Construction F Ameren Person(s) On Job Site			

Description of Construction:

Staff witnessed an Ameren crew installing a new long side service. Techniques used to perform these tasks were directional boring, excavating, electro fusing, and pressure testing.

SERVICE INSTALLATION		Status
[192.55]	Steel	No
[192.59]	PE	Yes
[192.59]	Other	No
[192.619,192.621,192.623]	MAOP	60 PSI
[192.5]	Class location :	Class 1
[192.53]	Are components qualified for use?	Satisfactory
[192.63(a)(2)]	Pipe Size :	1/2 and 2 inch

AMEREN ILLINOIS COMPANY/2-27-2014

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

[192.55,192.59]	Specification :	ASTM D 2513
[192.55,192.59]	Manufacturer :	DriscoPlex
[192.55,192.59]	Pipe Grade :	PE 2406
[192.55,192.59]	Wall Thickness :	0.09
[192.63]	Are pipe, valves, and fittings properly marked for identification?	Satisfactory
[192.227]	Welder qualification date:	Not Applicable
General Comment:		
Staff only observed plastic pipe being installed at this load	cation.	
[192.227]	Welder's Name:	Not Applicable
General Comment:		
Staff only observed plastic pipe being installed at this lo	cation.	
[192.225,192.275,192.277,192.279,192.283]	Is pipe joined in accordance with approved written procedures?	Satisfactory
[192.285]	Date of Qualification:	3/13/13
[192.285]	Joiner's name:	Shaun Hattan
[192.455]	Is buried metallic pipe coated?	Not Applicable
General Comment:		
Staff only observed plastic pipe being installed at this lo	cation.	
[192.455(a)(1)]	Is cathodic protection being provided?	Not Applicable
General Comment:		
Staff only observed plastic pipe being installed at this lo	cation.	
[192.455(a)(1)]	Is cathodic protection being provided? By Anodes:	No
[192.455(a)(1)]	Is cathodic protection being provided? By Rectifier:	No
[192.461]	Does coating meet 192.461?	Not Applicable
General Comment:		
Staff only observed plastic pipe being installed at this lo	cation.	
[192.461(c)]	Is coating inspected just prior to being installed in the ditch?	Not Applicable
General Comment:	·	
Staff only observed plastic pipe being installed at this lo	cation.	
[192.479]	Are above ground facilities cleaned and coated or jacketed as needed?	Not Applicable
General Comment:		

AMEREN ILLINOIS COMPANY/2-27-2014

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

Staff only observed plastic pipe being	installed at this location.	
[192.467]	Are pipelines electrically isolated from other underground metallic structures?	Not Applicable
General Comment:		
Staff only observed plastic pipe being	installed at this location.	
[192.319]	Is ditch back-filled to provide firm support and prevent damage to pipe or coating?	Satisfactory
[192.321(c)]	Is plastic pipe installed as to minimize shear and tensile forces?	Satisfactory
[192.321]	Does plastic pipe have means of locating while underground?	Satisfactory
General Comment:	<u> </u>	
Staff observed tracer wire being install	ed with the plastic pipe.	
[192.325]	Are required clearances from underground structures being maintained?	Satisfactory
General Comment:	<u> </u>	
Staff observed 12 inches from undergr	ound structures were being maintained.	
Is required cover being obtained for the service line?		Satisfactory
General Comment:		
Staff observed 18 inches of cover and	24 inches of cover under the street were being obtained for the service line.	
[192.503]	Are general testing requirements being met?	Satisfactory
General Comment:	<u>, </u>	
Staff observed a 100 PSI test that was	held for 10 min.	
[192.517]	Are records being made of strength and leak tests?	Satisfactory
General Comment:	,	
Staff reviewed the calibration date for the	the central electro fuser box which was 4/12 and is due on 6/14	
[192.807]	Were covered employees Operator Qualification records reviewed to ensure qualification?	Satisfactory
General Comment:	·	
Staff reviewed the OQ records for Sha	un Hattan and Allen Hoernis to install plastic pipe using directional boring.	
[192.805(c)]	Were non-qualified personnel being "directed and observed" by a qualified individual?	Not Applicable
General Comment:		
All individuals were qualified to do his/	her tasks.	
[192.805(c)]	Were span of control limitations being followed?	Not Applicable

AMEREN ILLINOIS COMPANY/2-27-2014

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

General Comment:		
All individuals were qualified to do his/her	tasks.	
Was a Protocol 9 (Form 15) Comp	pleted?	No
[192.614]	Were One Call Notifications performed as required?	Satisfactory
[192.614]	Dig Ticket #	X0510070
General Comment:		
Dig Start : 02/24/14 08:00:00 Expires : 03/19/14 23:59:00		
[192.383(b)]	Is an EFV installed on any new or replaced service line serving a single-family residence?	Satisfactory

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.